

In the Specification: (strikethrough parts deleted and underlined parts added)

On page 3, second full paragraph starting on line 15, please enter the following changes:

The main problem with conventional V-nail joiners is that they are difficult to operate and time consuming. A further problem with conventional V-nail joiners is that they can only insert a single V-nail into a frame joint. Another problem with conventional V-nail joiners is that sometimes they do not accurately position the V-nails within the frame joint.